

port.

Remove the phone cable from the "EXT." port and connect it to the "LINE"

Solution :

The phone cable is connected to the "EXT." port of the product.

Status :

1. Product Hardware Check	PASS
2. Phone Cable Connection Check	PASS
3. Connection Port Check	FAIL
4. Phone Line Connection Quality Check	----
5. Dial Tone Detection	----

Check Items

Name : Points and Pathways
Fax : 3606533403

Fax Diagnostic Report

Jan.21.2026 05:35 PM

PAGE. 001/001